

Contents of Firmware Changes (from D100 to D101)

No.	Description
1	Addition of mechanical initializing operation when power is on - The possibility that loading a disc cannot be performed smoothly when the power is turned on next time in case when the power is turned off during ejecting or when a disc is inserted forcibly while the power is not turned on was eliminated.
2	Improvement of DVD-R write quality - Improved write quality by optimizing Write Strategy for Panasonic DVD-R. With this action, yield at MKE manufacturing will improve.